

	TECHNICAL BULLETIN	Series	IMSA / USAC
		Page	1/1
		Date	3/11/26

Subject: Mustang Dark Horse R Front Caliper Grub Screw:

This bulletin is intended to highlight the grub screws located in six places on the front brake calipers of the Mustang Dark Horse R.

These screws must not be adjusted, loosened, or tightened under any circumstances. They are factory-installed permanent components and are not to be manipulated.

Using a hex key or any other tool on these screws may alter the factory torque and/or damage the screw. Doing this can damage the caliper and may result in a fluid leak, which will render the caliper unusable.

In some cases, a dust may accumulate around the screw area. This is especially apparent on the top of the caliper. This is typically caused by excess permanent thread lock used during assembly, which can remain on the external surface of the caliper body and attract dust. This condition is cosmetic only and does not indicate a problem with the caliper.

No action is required. Do not manipulate these screws.

